

SERVICE PARTS LIST

AKD 5230

III. No.	Part No.	DESCRIPTION	Qty.	Change Point	REMARKS
TOOLS					
1	AXE 425	Bag-tool	1		
2	AXE 429	Spanner— $\frac{5}{8}$ " x $\frac{9}{16}$ "	1		
3	AXE 430	Spanner— $\frac{1}{2}$ " x $\frac{7}{16}$ "	1		
4	2H 4614	Screwdriver	1		
5	AXE 427	Wheelbrace	1		
6	AXE 428	Spanner	1		
7	AXE 426	Jack—lifting	1		